

251202 – Item 17 – Memorial Quote

Quote received from F. J. Stevens & Son Ltd

Make safe the failed memorials:

There are 19 jobs which have failed (not including the ones which we laid down whilst on site).

As your aware there are several crosses which are fairly easy to part and lay down neatly within the grave space.

The monolith style stones require a little more time as they will need to be dug out and reinstalled to the required depth to comply with BS8415.

The Georgina Blackmore stone again requires a bit more attention due to the large void within the kerbing enclosure.

Minimum of 2 days probably 3 days' work for 2 people

Travel to Moretonhampstead and make safe the 19 memorials which have failed the safety inspections.

Including all travel, labour, and vat £1464.00